

DATE 0130Z 03 OCT 63

SECRET

TO : DIRECTOR

FROM : [REDACTED] 25X1A

ACTION: OSA 1-15

INFO :

TOR: 0535Z 03 OCT 63  
25X1A

EDD \_\_\_\_\_  
WER \_\_\_\_\_  
RDO \_\_\_\_\_  
RLP \_\_\_\_\_  
KB \_\_\_\_\_  
SHI \_\_\_\_\_  
PGS \_\_\_\_\_

25X1A

ROUTINE

IN 93817

TO

INFO

3014

25X1A  
MAINTENANCE REPORT FOR [REDACTED], 25 SEPT 1963.

1. SYSTEM III REPEAT SYSTEM III:

- A. RECEIVER A - NORMAL OPERATION.
- B. RECEIVER B - INTERMITTENT KEY PULSE (04 OR 05 BOARD FAILURE)
- C. RECEIVER C - NORMAL OPERATION. NOTE: IN SOME CASES THE DIFFERENCE BETWEEN MAXIMUM AND MINIMUM RECEIVER SENSITIVITY IS TOO LARGE. 5 TO 7 DB SHOULD BE THE MAXIMUM DIFFERENCE IN THE RECEIVER SENSITIVITIES.

2. "B" UNIT: NORMAL OPERATION.

END OF MESSAGE

SECRET